

Labor and Materials

2" Copper	Lead	Connection	\$		
.....	Curb	{ Cock Valve T. S. & V. in	\$		
.....	Service Box		{ Short 3½ x 4½ Long 4½ x 5½ Buff. or Rdway	\$	
.....	Old returned					
20	Ft.	{ Copper Galv Iron Cast Iron	2 in.	Pipe at	\$	
.....	Nipples	 in. at	\$	
.....	Bushings to in. at	\$	
.....	Red'g Inc'g	{ Couplings..... to in. at	\$	
.....	Union	 in. at	\$	
.....	Meter in. at	\$		
.....	Lead Joints	at	\$		
.....	Leadite Joints	at	\$		
.....	Hrs. Foreman	at	\$		
.....	Hrs. Chauffeur	at	\$		
.....	Hrs. Tapper	at	\$		
.....	Hrs. Labor	at	\$		
.....	Hrs. Labor	at	\$		
.....	Hrs. Compressor	at	\$		
.....	Compensation Ins.	\$		
.....	Trucking	\$		
.....	Builders Use of Water	\$		
.....			\$		
.....			\$		
.....			\$		
.....			\$		
.....			\$		
.....			\$		
.....			\$		

Kensington Court Bldg.

St:
Pl:
Ave. No. 11

Horicon

Name of Owner

Labor and Mat'l. Report *April 1-38* 19

● Curb Box

16" Main Kensington Rd. Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

SEE 21-27 KENSINGTON RD.

23' 23'