

Labor and Materials

Copper	}	Connection.....	\$	
Lead				
Curb	{	Cock Valve	\$	} gate Valve
		T. S. & V.		
1 Service Box	{	Short 3½ x 4½	\$	}
Old returned		Long 4½ x 5½		
		Buff. or Rdway		
3/4 Ft. in.		Copper	\$	} Pipe at
		Galv-Iron		
		Cast-Iron		
Nipples		in. at	\$	
Bushings		to in. at	\$	
Red'g	}	Conplings	to in. at	\$
Inc'g				
Union		in. at	\$	
Meter		in. at	\$	
Lead Joints		at	\$	
Leadite Joints		at	\$	
Hrs. Foreman		at	\$	
Hrs. Chauffeur		at	\$	
Hrs. Tapper		at	\$	
Hrs. Labor		at	\$	
Hrs. Labor		at	\$	
Hrs. Compressor		at	\$	
Compensation Ins.			\$	
Trucking			\$	
Builders Use of Water			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. Pt. Ave. No. 3

Horicon

Name of Owner
Barker, J.H.

renewal Tap
July 1983

Labor and Mat'l. Report 1983

Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box

gate Valve
renewal Tap
Put in same measurements