

Labor and Materials

Copper } Connection	2		
Lead } Connection	2		\$ 2.60
Curb } Cock Valve	2	1/4	
T. S. & V. }			\$ 2.30
Service Box } Short 3/4 x 1/2			
Old returned } Long 4 1/2 x 5 1/2			\$ 1.50
			Buff on Rdway
5 Ft. in. } Copper	8		
			\$ 1.33
			Cast Iron
Nipples			\$
Bushings			\$
Red'g } Couplings			\$
Inc'g }			\$
Union			\$
Meter			\$
Lbs. Br. Stone			\$
Lbs. Sand			\$
Bags Cement			\$
Paving Brick } Mack			\$
Asphalt }			\$
Lead Joints			\$
Leadite Joints			\$
2 Hrs. Foreman			\$ 1.25
4 Hrs. Common Labor			\$ 1.63
Hrs. Common Labor			\$
Hrs. Mason			\$
Hrs. Mason's Helper			\$
Hrs. Compressor			\$
Compensation Ins.			\$.08
Trucking			\$ 1.00
Builders' Use of Water	Patch		\$ 5.00
Total			\$ 16.67

Labor and Material Report May 15 1929

Horicon Ave Hny

● Curb Box

Main Elev of Main at tap *5.5*

Gate at ● ● Gate at

● Curb Box

Left hand side

Horicon Ave Hny

6" Main 5.5 elev of main tap

Left hand side