

Labor and Materials

Copper } Connection.....	2.70
Lead }	
Curb } Cock Valve }	2.39
} T.S. & V. }	
Service Box } Short 3 1/2 x 4 1/2 }	1.45
Old returned } Long 4 1/2 x 5 1/2 }	
} Buff. or Rdway }	
5 Ft. } in. } Copper } Pipe at.....	6.75
} } Galv. Iron }	
} } Cast Iron }	
Nipples..... in. at.....	\$
Bushings..... to..... in. at.....	\$
Red'g } Couplings..... to..... in. at.....	\$
Inc'g }	
Union..... in. at.....	\$
Meter..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement 'at.....	\$
Paving Brick } Mack } at.....	\$
} Red }	
} Asphalt }	
Lead Joints at.....	\$
Leadite Joints at.....	\$
3 Hrs. Foreman at.....	1.88
16 Hrs. Common Labor at.....	7.20
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	.28
Trucking.....	.1-
Builders' Use of Water Patch.....	.5-
Total \$	28.65

30-120

Labor and Material Report

Sept 15 1930

4 Hoyt Ave



● Curb Box

4 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

Old Tap disconnected