

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$		\$ 1.23
1	Lead				
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.		\$ 1.68
1	Service Box	Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway		\$ 1.54
25	Ft.		$\frac{3}{4}$ in.	Copper Galv-Iron Cast-Iron	Pipe at 17 \$ 4.25
	Nipples		in. at		\$
	Bushings		to in. at		\$
	Red'g Inc'g	Couplings	to in. at		\$
	Union		in. at		\$
	Meter		in. at		\$
	Lead Joints		at		\$
	Leadite Joints		at		\$
	Hrs. Foreman		at		\$
7	Hrs. Chauffeur		at 6 1/2 hr		\$ 4.38
4	Hrs. Tapper		at 1		\$ 2.60
10	Hrs. Labor		at 4 1/2		\$ 4.50
	Hrs. Labor		at		\$
	Hrs. Compressor		at		\$
	Compensation Ins.				\$.35
	Trucking				\$ 1.-
	Builders Use of Water	Patch			\$ 5.-
	Tap by Pallas				\$
					\$
					\$
					\$
					\$
					\$
					\$ 26.43

6 1 - - 1939

St. 12
Pr. 8
Ave. No. 8

Name of Owner

J. F. Lawrence

Labor and Mat'l. Report

Aug 17 1939



● Curb Box

4 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

TAX ID # 302.16-14-10

● Curb Box

old shut off