

**Labor and Materials**

Lead Connection	.....	\$
Curb Cock	.....	\$
Service Box (Short 3 1/2 x 4)	.....	\$
Old returned (Long 4 1/2 x 5)	.....	\$
Buffalo	.....	\$
8 Ft. 1/2 in. G. I. Pipe at	.....	\$
Nipples.....in. at	.....	\$
Bushings.....to.....in. at	.....	\$
Red'g Coup.....to.....in. at	.....	\$
Inc'g Coup.....to.....in. at	.....	\$
Union.....in. at	.....	\$
Meter.....in. at	.....	\$
Cu. Yds. Br. Stone at	.....	\$
Cu. Yds. Sand at	.....	\$
Bags Cement at	.....	\$
Paving Brick { Mack Red Asphalt } at	.....	\$
1 Hrs. Foreman at	.....	\$
1 Hrs. Common Labor at	.....	\$
Hrs. Mason at	.....	\$
Hrs.....at	.....	\$
Hrs.....at	.....	\$
Builders' Use of Water	.....	\$
Truck 100	.....	\$
.....at	.....	\$
.....at	.....	\$
.....at	.....	\$
Total	\$ 10.170	

59 26 1924  
 Labor and Material Report

49 Hudson Ave

House to be RATED

59

6

15-7

Curb Box

Shut off A CURB 7-14-22

---

C Main Elev. of Main at tap 5

Gate at ● Gate at ●

---

Curb Box

15'6"

Curb Box

NYT Pole #12

S.E. →