

LABOR AND MATERIALS

Same
 Copper } Connection 3/4" \$
 Lead }
 1 Curb } Cock } 3/4 in. \$
 } Valve }
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 }
 } Buff or Rdway } \$
 13 Ft. 3/4 in. { Copper } Pipe at \$
 } G.I. }
 } G.I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man-1 at \$
 Hrs. Water Maint. Man-2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 Change over \$
 by G. S. Gird & Co. \$
 6-2-60. \$
 O'head \$
 Note: - \$
 Used Same Tap. \$
 changed pipe from \$
 drive way to front of \$
 House. \$

Hudson St. Pl. Ave. No. 67

Name of Owner Berkowitz

Labor and Mat'l. Report June 2 1960

