

Labor and Materials

1	Copper	} Connection... 3/4	\$ 1.75
1	Lead			
1	Curb	} Cock Valve T.S.&V. } 3/4 in	\$ 1.70
1	Service Box			
1	Old returned	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff. or Rdw. }	\$ 1.37
16	Ft. 3/4 in.			
		} Copper Galv. Iron } Cast Iron }	Pipe at 1 1/2	\$ 2.43
	Nipples.....			
	Bushings.....	to.....	in. at.....	\$.....
	Red'g Inc'g	} Couplings.....	to.....	in. at.....
	Union.....			
	Meter.....	in. at.....	\$.....	
	Lbs. Br. Stone at.....	\$.....		
	Lbs. Sand at.....	\$.....		
	Bags Cement at.....	\$.....		
	Paving Brick	} Mack Red Asphalt }	at.....	\$.....
	Lead Joints at.....			
	Leadite Joints at.....	\$.....		
6	Hrs. Foreman at.....	62 1/2	\$ 3.75	
3	Hrs. Common Labor at.....	50	\$ 1.50	
9	Hrs. Common Labor at.....	45	\$ 4.05	
	Hrs. Mason at.....	\$.....		
	Hrs. Masons Helper at.....	\$.....		
	Hrs. Compressor at.....	\$.....		
	Compensation Ins.....	\$.35		
	Trucking.....	\$ 1.-		
	Builder's Use of Water.....	\$.....		

Total \$ 17.40..

335-11 14

Labor and Material Report *Apr 11* 19*05*

3/4" tap at 10 Hunter st

4 Main Elev of Main at tap *4 1/2*

Gate at ● ● Gate at

● Curb Box

Old tap shut off at main

OK

[Signature]