

**Labor and Materials**

Copper } Connection.....	\$.....
Lead } .....	\$.....
Curb { Cock Valve T.S.&V. } .....	in ..... \$.....
Service Box { Short 3½x4½ Long 4½x5½ } .....	\$.....
Old returned { Buff. or Rdway } .....	\$.....
Ft..... in. { Copper Galv. Iron Cast Iron } Pipe at .....	\$.....
Nipples ..... in. at .....	\$.....
Bushings ..... to ..... in. at.....	\$.....
Red'g } Couplings..... to..... in.at.....	\$.....
Inc'g } .....	\$.....
Union..... in. at .....	\$.....
Meter..... in. at .....	\$.....
Lbs. Br. Stone at .....	\$.....
Lbs. Sand at .....	\$.....
Bags Cement at .....	\$.....
Paving Brick { Mack Red Asphalt } at .....	\$.....
Lead Joints at .....	\$.....
Leadite Joints at .....	\$.....
Hrs. Foreman at .....	\$.....
Hrs. Common Labor at .....	\$.....
Hrs. Common Labor at .....	\$.....
Hrs. Mason at .....	\$.....
Hrs. Masons Helper at .....	\$.....
Hrs. Compressor at .....	\$.....
Compensation Ins .....	\$.....
Trucking .....	\$.....
Builders Use of Water .....	\$.....
Total \$.....	

21B

Labor and Material Report *Apr 16* 19*35*

Hunter at

Measurement for rear House at 19½ Hunter at

21B

19 Hunter at

Curb Box

---

Main Elev. of Main at tap \_\_\_\_\_

---

Gate at ● ● Gate at

---

● Curb Box

Curb Box for 19½ Hunter at