

Labor and Materials

1	Copper } Connection ^{3/4}	\$ 3.20
	Lead	
1	Curb { Cock } ^{3/4} in.	\$ 1.00
	{ Valve }	
	{ P.S. & V. }	
1	Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.30
	Old returned { Long 4 1/2 x 5 1/2 }	
	{ Buff. or Rdway }	
21	Ft. ^{3/4} in. { Copper } Pipe at.	\$ 4.62
	{ Galv. Iron }	
	{ Cast Iron }	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack } at.....	\$
	{ Red }	
	{ Asphalt }	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
2	Hrs. Foreman at.....	\$ 1.25
	Hrs. Common Labor at.....	\$
15	Hrs. Common Labor at ^{40 1/2}	\$ 6.09
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 1.9
	Trucking.....	\$ 1.00
	Builders' Use of Water.....	\$

Total \$ 18.65

27-219

22

Labor and Material Report

Dec 2

19 27

#16 Hunter St



6" Main

Elev. of Main at tap 4 ft

Gate at ●

● Gate at

● Curb Box

Old shut off