

Labor and Materials

Copper } Connection		\$ 2.70	
Lead } Connection			
Curb } Cock	in.	\$ 2.39	
Valve } P. S. & V.			
Service Box } Short 3 1/2 x 4 1/2	}	\$ 1.45	
Old returned } Long 4 1/2 x 5 1/2			
	By or Redway		
9 Ft. in.	Copper Galvanized Pipe at	\$ 2.43	
	Cast Iron		
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g Inc'g } Couplings	to in. at	\$	
Union	in. at	\$	
Meter	in. at	\$	
Lbs. Br. Stone	at	\$	
Lbs. Sand	at	\$	
Bags Cement	at	\$	
Paving Brick } Mack	} at	\$	
			Red
			Asphalt
Lead Joints	at	\$	
Leadite Joints	at	\$	
6 Hrs. Foreman	at	\$ 5.75	
16 Hrs. Common Labor	at	\$ 7.20	
Hrs. Common Labor	at	\$	
Hrs. Mason	at	\$	
Hrs. Mason's Helper	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins		\$.34	
Trucking		\$ 1.-	
Builders' Use of Water		\$	
Total		\$ 71.26	

31-9 25- 21 1931
 Labor and Material Report

23

26' 8" 25" 28' Curb Box

6 Main Elev of Main at tap 5 1/2

Gate at ● Gate at ●

● Curb Box

old Tap
 shut off