

Labor and Materials

Copper } Connection.....	3	\$ 2.70
Lead }		
Curb } Cock Valve }	3 4	\$ 2.39
T.S. & V. }	4	
Service Box } Short 3/4x4 1/2 }		\$ 1.45
Old returned } Long 4 1/2x5 1/2 }		
Buff. or Rdway }		
22 Ft. } in. } Copper } Galv. Iron } Cast Iron } Pipe at.....	3 4	\$ 5.94
Nipples.....	in. at.....	\$.....
Bushings.....	to..... in. at.....	\$.....
Red'g } Couplings.....	to..... in. at.....	\$.....
Inc'g }		
Union.....	in. at.....	\$.....
Meter.....	in. at.....	\$.....
Lbs. Br. Stone at.....		\$.....
Lbs. Sand at.....		\$.....
Bags Cement at.....		\$.....
Paving Brick } Mack } Red } Asphalt } at.....		\$.....
Lead Joints at.....		\$.....
Leadite Joints at.....		\$.....
4 Hrs. Foreman at.....		\$ 2.50
4 Hrs. Common Labor at.....	Tapper	\$ 2. --
9 Hrs. Common Labor at.....		\$ 3.60
Hrs. Mason at.....		\$.....
Hrs. Mason's Helper at.....		\$.....
2 Hrs. Compressor at.....		\$ 3. --
Compensation Ins.....		\$.75
Trucking.....		\$ 1. --
Builders' Use of Water.....	Patch	\$ 5. --
Total \$		29.83

30-153

28713

Oct. 25 1930

Labor and Material Report

22 Hunter St



21' 4"

Curb Box

33' 2"

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

Old tap to be dug up
 Measured in from each corner of the porch.