

Labor and Materials

1	Copper	} Connection ^{3/4}	\$ 1.25
	Lead			
1	Curb	} Cock Valve T.S.&V. } .3/4 in	\$ 1.70
1	Service Box	} Short 3 1/2 x 4 1/2 } } Long 4 1/2 x 5 1/2 } } Old returned Buff or Raw	\$ 1.37
1.0	Ft. ^{3/4} in.	} Copper } } Galv. Iron } } Cast Iron }	Pipe at 12 1/2	\$ 1.25
	Nipples in. at		\$
1	Bushings	3/4 to 1/2 in. at		\$.05
	Red'g Inc'g	} Couplings.....to.....in. at		\$
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	} Mack } } Red } } Asphalt }	at	\$
	Lead Joints		at	
	Leadite Joints	at		\$
5	Hrs. Foreman	at 6 1/2 hr		\$ 3.13
1	Hrs. Common Labor	at		\$.50
5	Hrs. Common Labor	at 45		\$ 2.25
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$.22
	Trucking			\$ 1.-
	Builders Use of Water			\$

Total \$ 17.87

1935 - 44

31

Labor and Material Report

Apr 16

1935

3/4 tap at 2 7/2 Hunter st



4 Main

Elev. of Main at tap 4 1/2

Gate at

Gate at

TAX ID # 302.16-15-8

Curb Box

Old tap shut off at main

Disconnected at
MAIN - MAR-23-1972

[Signature]