

**Labor and Materials**

1	Copper	} Connection <sup>3/4</sup>		\$ 1.25
1	Lead			
1	Curb	} Cock Valve T.S.&V. } <sup>3/4</sup> in		\$ 1.70
1	Service Box Old returned		} Short <del>3 1/2</del> x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff or Ridger }	
10	Ft. <sup>3/4</sup> in.	} Copper Galv. Iron Cast Iron } Pipe at <sup>1 3/4</sup>		
	Nipples			
1	Bushings <sup>3/4</sup> to <sup>1/2</sup>			\$ .05
	Red'g Inc'g	} Couplings.....to.....in.at		\$
	Union			
	Meter			\$
	Lbs. Br. Stone			\$
	Lbs. Sand			\$
	Bags Cement			\$
	Paving Brick	} Mack Red Asphalt }		\$
	Lead Joints			
	Leadite Joints			\$
7	Hrs. Foreman		<sup>62 1/2</sup>	\$ 4.38
3	Hrs. Common Labor		<sup>50</sup>	\$ 1.50
10	Hrs. Common Labor		<sup>45</sup>	\$ 4.50
	Hrs. Mason			\$
	Hrs. Masons Helper			\$
	Hrs. Compressor			\$
	Compensation Ins			\$ .39
	Trucking			\$ 1.-
	Builders Use of Water			\$

Total \$ 17.51...

1935-45

34

Labor and Material Report Apr 17

1935

*3/4" tap at 28 Hunter st*

P 34



● Curb Box

4 Main

Elev. of Main at tap <sup>4 1/2</sup>

Gate at ●

● Gate at

● Curb Box

*Old tap shut off at main*

TAX ID # 302.16-13-39

*[Handwritten signature]*