

Labor and Materials

2	Copper	} Connection. $\frac{3}{4}$	\$ 1.25
	Lead			
1	Curb	} $\frac{3}{4}$ in	\$ 1.70
	{ Cock Valve T.S.&V.			
1	Service Box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdwa.	\$ 1.37
	Old returned			
10 Ft.	$\frac{3}{4}$ in.	} Copper Galv. Iron Cast Iron	Pipe at $1\frac{3}{4}$	\$ 1.35
	Nipples			
	Bushingsto.....in. at.....	\$	
	Red'g Inc'g	} Couplings.....to.....in. at.....	\$	
	Union			
	Meterin. at.....	\$	
	Lbs. Br. Stone	at.....	\$	
	Lbs. Sand	at.....	\$	
	Bags Cement	at.....	\$	
	Paving Brick	} Mack Red Asphalt	at.....	\$
	Lead Joints			
	Leadite Joints	at.....	\$	
5	Hrs. Foreman	at.....	\$ 3.13	
1	Hrs. Common Labor	at.....	\$.38	
5	Hrs. Common Labor	at .45	\$ 2.25	
	Hrs. Mason	at.....	\$	
	Hrs. Masons Helper	at.....	\$	
	Hrs. Compressor	at.....	\$	
	Compensation Ins	\$.22	
	Trucking	\$ 1	
	Builders Use of Water	\$	
Total \$				12.77

1935-50

Labor and Material Report *Apr 18* 19 *33*

33 Hunter St



4 Main

Elev. of Main at tap $4\frac{1}{2}$

Gate at ●

● Gate at

● Curb Box

old shut off of main

[Signature]