

Labor and Materials

1	Copper	Connection	3	\$ 3.20
1	Curb	Cock Valve T.S. & V.	1	\$ 1.00
	Service Box	Short 3 1/2 x 4 1/2		\$ 1.30
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
1 1/2	Ft.	Copper Galv. Iron Cast Iron	3	\$ 5.06
	Nipples	in. at		\$
	Bushings	to in. at		\$
1	Red'g. Inc'g.	Couplings	3/4 to	\$ 1.5
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at	1.25	\$ 1.25
12	Hrs. Common Labor	at	50	\$ 6.00
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 1.20
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 19.16

26-69 41 July 6 1916

Labor and Material Report

11-35 Hunter St.

Elev. of Main at tap 52'

Gate at ● Gate at ●

TAX ID # 302.16-16-8

● Curb Box

Check for old service on Hunter

old tap to be dug up.

S. J. ...

Hunter St on left
34' 7" 24' 5"