

Labor and Materials

| | | | |
|------------------------|---------------------------|------|----------|
| Copper | Connection | 3 | \$ 2.60 |
| Curb | Cock | 1 | \$ 2.30 |
| Service Box | Short 3/4x4 1/2 | 4 | \$ 1.40 |
| Old returned | Long 4x5 1/2 | | |
| | Buff. or Redway | | |
| 25 Ft. | Copper Galv. Iron Pipe at | 3 | \$ 6.63 |
| | Cast Iron | 9 | |
| Nipples | in. at | | \$. |
| Bushings | 1/2 to 1 in. at | | \$.10 |
| Red'g Inc'g | Couplings to in. at | | \$. |
| Union | in. at | | \$. |
| Meter | in. at | | \$. |
| Lbs. Br. Stone | at | | \$. |
| Lbs. Sand | at | | \$. |
| Bags Cement | at | | \$. |
| Paving Brick | Mack Red Asphalt at | | \$. |
| Lead Joints | at | | \$. |
| Leadite Joints | at | | \$. |
| 2 Hrs. | Foreman at | | \$ 1.25 |
| 17 Hrs. | Common Labor at | | \$ 7.31 |
| Hrs. | Common Labor at | | \$. |
| Hrs. | Mason at | | \$. |
| Hrs. | Mason's Helper at | | \$. |
| Hrs. | Compressor at | | \$. |
| Compensation Ins. | | 23 | \$ 23 |
| Trucking | | 1.00 | \$ 1.00 |
| Builders' Use of Water | Table | 5.00 | \$ 5.00 |
| Total | | | \$ 27.82 |

29-12A 46 July 29 1929
 Labor and Material Report

40 Hunter St.



Curb Box

4 Main Elev of Main at tap 5 1/2

Gate at ● Gate at ●
 TAX ID # 302.16-14-22

● Curb Box

old tap shut off
 at main