

LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$ " \$
~~Lead~~

1 Curb { Cock Valve } $\frac{3}{4}$ in. \$
 { T. S. & V. }

1 Service Box { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } \$
 Old returned { Long $4\frac{1}{2} \times 5\frac{1}{2}$ }
 { Buff. or Rdway }

29 Ft. $\frac{3}{4}$ in. { Copper } Pipe at \$
 { Galv Iron }
 { Cast Iron }

Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }

Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 Tap by Lareau & Co. \$
 Jan. 27-67. \$
 \$
 \$

St. *71A-B*
 Pt. *Hunter*
 Ave. No. *65*

Name of Owner
 TAX ID # 303.13-8-13

Labor and Mat'l. Report *Jan. 27 1967*



4" Main Elev. of Main at tap *4'*
 Gate at ● Gate at ●

● Curb Box