

LABOR AND MATERIALS

1	Copper Lead	{ Connection 3/4"	\$ 3.04
1	Curb	{ Cock Valve T.S. & V. } 3/4" in.	\$ 3.54
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }	\$ 4.70
17	Ft. 3/4 in.	{ Copper C.I. C.I. } Pipe at 35	\$ 5.95
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	{ Coupl'gs to in. at }	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints at		\$
	Compound Joints at		\$
	Hrs. Water Maint. Man-1 at		\$
12	Hrs. Water Maint. Man-2 at	1.13	\$ 13.56
29	Hrs. Labor <sup>2</sup> at	1.02	\$ 10.58
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
	Compensation Ins. at \$ 2.66 per C.		\$ 64
	Trucking		\$ 1.02
	Pay't Patch		\$ 25.65
	Tap by Moquin		\$
	O'head		\$
			\$ 68.66

10-1951

Hunter St. Pl: Ave. No. 73

Name of Owner Pepper

Labor and Mat'l. Report Dec 12 1950

6" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

● Curb Box

LSM-SC 10-21-49