

Labor and Materials

Copper } Connection.....	\$
Lead } Connection.....	\$
Curb { Cock Valve } 1" in.....	\$
	T-S. & V. }
Service Box { Short 3½ x 4½ }.....	\$
Old returned { Long 4½ x 5½ }.....	\$
	Buff. or Rdway }
12 Ft. 1" in. { Copper } Pipe at.....	\$ 25
	Galv. Iron }
	Cast Iron }
1 Nipples 1" in. at.....	\$
1 Bushings 1" to..... in. at.....	\$
Red'g } Couplings..... to..... in. at.....	\$
Inc'g }	
1 Union..... in. at.....	\$
1 Meter..... in. at.....	\$
1 Lbs. Br. Stone at.....	\$
1 Lbs. Sand at.....	\$
1 Bags Cement at.....	\$
1 Paving Brick { Mack } at.....	\$
	Red }
	Asphalt }
1 Lead Joints at.....	\$
1 Leadite Joints at.....	\$
2 Hrs. Foreman at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$
Trucking.....	\$
Builders' Use of Water.....	\$
Total \$.....	

77 Labor and Material Report

19

Making material for repairs at 69th & Hunter at

77



Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

Labor and Materials

1	Copper Lead	} Connection	3/4		\$ 32.00
1	Curb	{ Cock Valve T. S. & V. }	3/4	in.	\$ 10.00
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }			\$ 13.00
26	Ft.	{ Copper Galv. Iron Cast Iron }	3/4	in. } Pipe at	22 \$ 57.20
	Nipples	in. at			\$
	Bushings	to		in. at	\$
1	Red'g Inc'g	{ Couplings	3/4	to	\$ 15
	Union	in. at			\$
	Meter	in. at			\$
	Lbs. Br. Stone	at			\$
	Lbs. Sand	at			\$
	Bags Cement	at			\$
	Paving Brick	{ Mack Red Asphalt }		at	\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
8	Hrs. Common Labor	at	50		\$ 4.00
6	Hrs. Common Labor	at	46 3/8		\$ 24.43
	Hrs. Mason	at			\$
	Hrs. Mason's Helper	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$ 18
	Trucking				\$ 10.00
	Builders' Use of Water				\$
Total					\$ 189.88

Labor and Material Report

July 9 1916

no 69? Hunter 20
no machine used

● Curb Box

14" Main

Elev. of
Main at tap 4'

Gate at ●

● Gate at

● Curb Box