

**Labor and Materials**

1	Copper } Connection		\$
1	Lead } Connection		\$
1	Curb } Cock		\$
	} Valve	in.	\$
	} T.S. & V.		\$
1	Service Box } Short 3 1/2 x 4 1/2		\$
	} Old returned } Long 4 1/2 x 5 1/2		\$
	} Buff. or Rdway.		\$
8	Ft. } in.	Copper } Pipe at	\$
	} in. at.	Galv. Iron } Pipe at	\$
	} in. at.	Cast Iron }	\$
	Nipples	in. at.	\$
	Bushings	to..... in. at.	\$
	Red'g } Couplings	to..... in. at.	\$
	Inc'g }		\$
	Union	in. at.	\$
	Meter	in. at.	\$
	Lbs. Br. Stone	at.	\$
	Lbs. Sand	at.	\$
	Bags Cement	at.	\$
	Paving Brick } Mack	} at	\$
	} Red		
	} Asphalt		\$
	Lead Joints	at.	\$
	Leadite Joints	at.	\$
1	Hrs. Foreman	at.	\$
1	Hrs. Common Labor	at. 50	\$
8	Hrs. Common Labor	at.	\$
	Hrs. Mason	at.	\$
	Hrs. Mason's Helper	at.	\$
	Hrs. Compressor	at.	\$
	Compensation Ins.		\$
	Trucking		\$
	Builders' Use of Water		\$
	<b>Total</b>	\$	

27-218 *125*  
**Labor and Material Report** *Nov 22* 19 *27*  
*drw 113 East*



6" Main Elev. of Main at tap 5'  
 Gate at ● Gate at ●



