

LABOR AND MATERIALS

1 Copper } Connection ^{3/4"} \$ _____
 Lead }
 1 Curb } Cock } 3/4" in. \$ _____
 } Valve }
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 } Same
 Old returned { Long 4 1/2 x 5 1/2 }
 { Buff. or Rdway } \$ _____
 20 Ft. ^{3/4} in. { Copper } Pipe at \$ _____
 { G.I. }
 { C.I. }
 Nipples _____ in. at \$ _____
 Bushings _____ to _____ in. at \$ _____
 Red'g }
 Inc'g } Coupl'gs. _____ to _____ in. at \$ _____
 Union _____ in. at \$ _____
 Meter _____ in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman _____ \$ _____
 Hrs. Water Maint. Man—1 at \$ _____
 Hrs. Water Maint. Man—2 at \$ _____
 Hrs. Garage Foreman _____ at \$ _____
 Hrs. Labor _____ at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C \$ _____
 Trucking _____ \$ _____
 Pav't Patch _____ \$ _____
 Tap by Gifford _____ \$ _____
 + Co. _____ \$ _____
 4-11-61. _____ \$ _____
 O'head _____ \$ _____
 \$ _____

St. _____
 Pt. _____
 Ave. No. 12

Hunter
 Name of Owner _____

Denton.

Labor and Mat'l. Report April 11 1961

● Curb Box

4" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM—5C—2-B 66