

Labor and Materials

Copper	Lead	Connection	3	\$ 1.33		
	Curb	Cock Valve T.S.V.	in	3/4		
						\$ 1.58
	Service Box	Short 3 1/2 x 4 1/2	}	\$ 1.36		
					Old returned	Long 4 1/2 x 5 1/2
17	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	Pipe at 19 1/2	\$ 1.62	
	Nipples	in.	at		\$	
	Bushings	to	in.	at	\$	
	Red'g Inc'g	Couplings	to	in.	at	\$
	Union	in.	at		\$	
	Meter	in.	at		\$	
	Lbs. Br. Stone	at			\$	
	Lbs. Sand	at			\$	
	Bags Cement	at			\$	
	Paving Brick	Mack Red Asphalt	at		\$	
	Lead Joints			at		\$
	Leadite Joints	at			\$	
3	Hrs.	Foreman	at		\$ 1.88	
3	Hrs.	Common Labor	at Tapper		\$ 1.50	
8	Hrs.	Common Labor	at		\$ 3.60	
	Hrs.	Mason	at		\$	
	Hrs.	Masons Helper	at		\$	
	Hrs.	Compressor	at		\$	
	Compensation Ins				\$ .22	
	Trucking				\$ 5-	
	Builders Use of Water	Batch			\$ 5-	
				Total	\$ 19.09	

33-69 23

Labor and Material Report Aug 31 1933

4 21/2 Day St

RAZED?

4 Main Elev. of Main at tap 5 1/2

Gate at • Gate at •

• Curb Box

Old Tap shut off at Main

Ins