

Labor and Materials

1	Copper	Connection	3	\$ 3.20
1	Curb	Cock Valve	in	\$ 1.00
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.40
	Old returned	Long 4 1/2 x 5 1/2		
		Buffer Rdway		
7	Ft.	Copper	Pipe at	\$ 1.54
	in.	Cast Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
1	Hrs. Foreman	at		\$ 6.40
5	Hrs. Common Labor	at		\$ 20.3
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 1.07
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 108.7

27-222

8

Labor and Material Report NOV.

1927

2 Johnson St



Main Elev. of Main at tap 116

Gate at ● ● Gate at

● Curb Box

old Tap Disconnected

Drug up