

LABOR AND MATERIALS

1	Copper Lead	} Connection ^{3/4"}	\$
1	Curb		} Cock Valve T.S. & V. } ^{3/4"} in.
1	Service box Old returned	} Short ^{3 1/2} x ^{4 1/2} Long ^{4 1/2} x ^{5 1/2} }	
7	Ft. ^{3/4"} in.		} { Copper G.I. C.I. } Pipe at
	Nipples	in. at	
	Bushings	to in. at	\$
	Red'g } Inc'g }	} Coupl'gs to in. at	\$
	Union		in. at
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor—	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. KATHERINE
~~Pt.~~
 Ave. No. 1

Name of Owner
M. KEITH

Labor and Mat'l. Report NOV. 1937



26' 7" 21' 7"

● Curb Box

12" Main (1969) Elev. of Main at tap 5.66'

Gate at ● ● Gate at

● Curb Box

26' 7" 21' 7"

12" main 1969

5' or 6'