

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$
	Lead			
1	Curb	} Cock Valve T.S. & V.	3/4" in.	\$
1	Service box	} Short 3 1/2 x 4 1/2		\$
	Old returned			
20	Ft. 3/4" in.	} Copper C.I. C.I.	} Pipe at	\$
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g Inc'g	} Coupl'gs	to in. at	\$
	Union	in. at	\$	
	Meter	in. at	\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

KATHERINE

St. ~~Pl.~~ Ave. No. 12

Name of Owner

Labór and Mat'l. Report APR. 1926



24'10" 16'9"

● Curb Box

12" Main (1969)

Elev. of Main at tap 5 to 6'

Gate at ●

● Gate at

● Curb Box

NOTE - THERE IS AN 1 1/2" SERVICE NEAR #12. KATHERINE - SEE NEXT CARD - FEEDS

BOATHOUSE