

LABOR AND MATERIALS

Copper	} Connection	_____	\$ _____	
Lead				
Curb	} Cock	_____ in.	\$ _____	
				} Valve
Service box	} Short 3½ x 4½	_____	\$ _____	
Old returned				Long 4½ x 5½
14 Ft. 1" in.	} Copper	} Pipe at	\$ _____	
				<del>C.I.</del>
Nipples	in. at	_____	\$ _____	
Bushings	to _____ in. at	_____	\$ _____	
Red'g } Inc'g }	} Coupl'gs	to _____ in. at	\$ _____	
Union				in. at
Meter	in. at	_____	\$ _____	
_____			\$ _____	
Compound Joints	at	_____	\$ _____	
Maintenance Foreman		_____	\$ _____	
Hrs. Water Maint. Man—1	at	_____	\$ _____	
Hrs. Water Maint. Man—2	at	_____	\$ _____	
Hrs. Garage Foreman	at	_____	\$ _____	
Hrs. Labor—	at	_____	\$ _____	
Hrs. Compressor	at	_____	\$ _____	
_____			\$ _____	
Trucking		_____	\$ _____	
Pav't Patch		_____	\$ _____	
_____			\$ _____	
_____			\$ _____	
_____			\$ _____	
_____			\$ _____	

St. KATHERINE  
 Pt. 15  
 Ave. No. \_\_\_\_\_

Name of Owner  
CIFONE - APT. HOUSE

Labor and Mat'l. Report 1991



● Curb Box

ROGERS ST.

Main Elev. of  
Main at tap

Gate at ● ● Gate at

● Curb Box

TAP ON ROGERS