

### LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/2 in.		\$ 13.10
1	Curb	Cock Valve F.S. & V.	1 1/2 in.		\$ 11.55
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway	4"		\$ 10.-
4	Ft. 1 1/2 in.	Copper C.I.	Pipe at	79	\$ 3.16
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Water Maint. Man	— 1 at			\$
10	Hrs. Water Maint. Man	— 2 at	1.02		\$ 10.20
4	Hrs. Labor	Mech	1.15		\$ 4.60
	Hrs. Labor	at			\$
6	Hrs. Compressor at		1.20		\$ 7.20
	Compensation Ins. at	\$ 2.22 per C.			\$ 33
	Trucking				\$
	Pav't Patch				\$
	Tap by Mansnick & Co.				\$
	O'head				\$
					\$ 60.14

St. \_\_\_\_\_  
 PT \_\_\_\_\_  
 Ave. No. \_\_\_\_\_

Katherine

---

Name of Owner  
*Recreation Commission*

---

Labor and Mat'l. Report *June 6* 1950

12  
Katherine St

RE MEASURED  
 by Brown & Co.  
 May 27, 75

39.8'

Curb Box

---

1969 ✓  
 12" Main 243'

KATHERINE ST.  
 Elev. of Main at tap 576'

---

Gate at Pole # NYP # 3

69.7' Gate at Pole # NYP # 1

---

GREER ST

Curb Box

Tap For Boat House  
 East Field  
 To be billed Playground.

LSM-5C 10-21-49