

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	in.	\$	
	Lead					
1	Curb	} Cock Valve T. S. & V.	3/4"	in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2	}		\$	
	Old returned					Long 4 1/2 x 5 1/2
7	Ft.	} Copper	3/4"	in.	\$	
						C.I.
						C.I.
	Nipples	in.	at	\$		
	Bushings	to	in.	at	\$	
	Red'g	} Coupl'gs	to	in.	at	
	Inc'g					
	Union	in.	at	\$		
	Meter	in.	at	\$		
				\$		
	Compound Joints	at	\$			
	Maintenance Foreman		\$			
	Hrs. Water Maint. Man-1	at	\$			
	Hrs. Water Maint. Man-2	at	\$			
	Hrs. Garage Foreman	at	\$			
	Hrs. Labor	at	\$			
	Hrs. Compressor	at	\$			
			\$			
	Trucking		\$			
	Pay't Patch		\$			
			\$			
			\$			
			\$			
			\$			

KATHERINE St. Ave. No. 3

Name of Owner TF KENNEDY

Labor and Mat'l. Report NOV 1937



27' 4" 21' 8"

● Curb Box

12" Main (1969) Elev. of Main at tap 5' 0 6'

Gate at ● Gate at

● Curb Box

LSM-5C-6-1-67

27' 4" 21' 8"

12" Main 1969 5' to 6'