

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"		\$ 1.35
1	Curb	Cock Valve T. S. & V.	3/4" in.		\$ 1.80
1	Service Box Old returned		Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$ 1.70
14	Ft.	3/4" in.	Copper Galv. Iron Cast Iron	Pipe at	\$ 2.52
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Leadite Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water	Before Tapping			\$
					\$
					\$
	Tap by Hassel				\$
					\$

48 1941

St. 7
Pl.
Ave. No. 2

Keenan

Name of Owner

Mrs Geo Cook

Labor and Mat'l. Report

Apr 24 1941



● Curb Box

6" Main

Elev. of
Main at tap 5'

Gate at ●

● Gate at

● Curb Box

TAX ID # 303.17-22-8

13
13

Labor and Materials

Copper	}	Connection.....	\$.....
Lead	}		
Curb	{	Cock Valve T. S. & V. in	\$.....
Service Box	{	Short 3½ x 4½	\$.....
Old returned	}	Long 4½ x 5½	
	}	Buff. or Rdway	
Ft. in.	{	Copper	} Pipe at
	}	Galv Iron	
	}	Cast Iron	
Nipples		in. at	\$.....
Bushings		to	\$.....
Red'g Inc'g	{	Conplings	\$.....
Union		in. at	\$.....
Meter		in. at	\$.....
Lead Joints at			\$.....
Leadite Joints at			\$.....
Hrs. Foreman at			\$.....
Hrs. Chauffeur at			\$.....
Hrs. Tapper at			\$.....
Hrs. Labor at			\$.....
Hrs. Labor at			\$.....
Hrs. Compressor at			\$.....
Compensation Ins.			\$.....
Trucking			\$.....
Builders Use of Water			\$.....
			\$.....
			\$.....
			\$.....
			\$.....
			\$.....

St. **7**
 Pl-
 Ave. No. **2**

Keenan

Name of Owner

Labor and Mat'l. Report 19



Main Elev. of
Main at tap

Gate at ● ● Gate at

● Curb Box