

Labor and Materials

1	Copper } Connection	2"	\$ 23.50
1	Curb } Cock	2"	\$ 15.40
		Valve }	
		T.S. & V. }	
1	Service Box } 4x4 } 4x4 } 4x4 }		\$ 2.63
		for Rdway }	
20	Ft. 2" in. } Copper } Galv. Iron } Pipe at } Cast Iron }		\$ 18.20
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack } Red } Asphalt }	at	\$
	Lead Joints at		\$
	Leadite Joints at		\$
1	Hrs. Foreman at		\$ 2.50
9	Hrs. Common Labor at		\$ 4.50
9	Hrs. Common Labor at		\$ 2.66
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins		\$ 1.28
	Trucking		\$ 1.00
	Builders' Use of Water	Patch	\$ 5.00
Total \$			76.67

Labor and Material Report 19 *22*

Kensington Court
 cor of Dixon Road
 & Horicon Ave.

Old Service to be dug up
 ● Curb Box

16 Main Elev of Main at tap 5

Gate at ● ● Gate at

● Curb Box

Kensington Court Corner of Dixon Road and Horicon Ave

Old service to be dug up

Labor and Material Report

19 22

Kingston Court
Cor. of Dixon Road
& American Ave

who had to be dug up
Curb Box

16 Main
Play of Main at tap

Gate at

Gate at

