

Labor and Materials

1	Copper Lead	Connection	\$ 2.60	
1	Curb	Cock Valve T. S. & V. in.	\$ 2.27	
1	Service Box	Short 3/4x4 1/2	}	\$ 1.38	
Old returned	Long 1 1/2x6 1/2	Buff or Rdway			
25	Pt.	Copper Galv. Iron Cast Iron	Pipe at	\$ 4.50	
	Nipples in. at		\$	
	Bushings to	in. at	\$	
	Red'g Inc'g	Couplings to	in. at	\$
	Union in. at		\$	
	Meter in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
3	Hrs. Foreman	at		\$ 1.88	
6	Hrs. Common Labor	at		\$ 2.70	
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.		\$ 14	
	Trucking		\$ 1 -	
	Builders' Use of Water	Patch		\$ 5 -	
Total \$				71.47	

31-237

4

Labor and Material Report

Mar

30 1931

2 Kenworthy Ave



4" Main

Eley of Main at tap

Gate at ●

● Gate at

● Curb Box

New House