

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
	Lead				
1	Curb	} T. S. & V.	3/4" in.	\$	
					Cock
					Valve
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				Long 4 1/2 x 5 1/2
		Buff or Rdway			
12	Ft.	} Pipe at	3/4 in.	\$	
					Copper
					G. I.
		C. I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs. to in. at		\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man—1 at			\$	
	Hrs. Water Maint. Man—2 at			\$	
	Hrs. Garage Foreman at			\$	
	Hrs. Labor— at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap by Gissard & Co.			\$	
	7-8-57,			\$	
	O'head			\$	
				\$	

✓

Kenworthy Ave. No. 15

Name of Owner Kilroy

Labor and Mat'l. Report July 8 19 57

15'

20'3"

33'5"

● Curb Box

4" Main

Elev. of Main at tap 4 1/2"

Gate at ●

● Gate at

TAX ID # 302.12-21-16

● Curb Box

LSM-5C-2-5 56