

LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$ " - \$
 Lead }
 1 Curb { Cock } $\frac{3}{4}$ in. \$
 Valve }
 T. S. & V. } *Orsival*
 1 Service Box { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } \$
 Old returned { Long $4\frac{1}{2} \times 6\frac{1}{2}$ } \$
 { Buff. or Rdway } \$
 27 $\frac{3}{4}$ Ft. in. { Copper } Pipe at \$
 { Galv. Iron }
 { Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 1 $\frac{3}{4}$ " Male Adapter in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 Tap by Giffard \$
 + Co. \$
 2-11-64 \$
 \$
 \$

St: 16
 Pl. *14*
 Ave. No. *14*

Kenworthy
 Name of Owner
Lawrence P. Mancini

Labor and Mat'l. Report *Feb. 11, 1964*



4" Main Elev. of Main at tap *5'*

Gate at ● Gate at ●

● Curb Box