

Labor and Materials

.....	Copper	Connection	\$ 2.60
.....	Lead			
.....	Curb	Cock Valve To S. & V. } ..in.	\$ 2.30
.....	Service Box	Short 3 1/2 x 4 1/2	\$ 1.40
.....	Old returned	Long 4 1/2 x 5 1/2	
.....		Buff. or Rdway	
.....	11 Ft.	Copper Pipe at	\$ 29.2
.....	Nipples	Cast Iron	
.....	Bushings	in. at	\$
.....	Red'g Inc'g	Couplings	\$
.....	Union	in. at	\$
.....	Meter	in. at	\$
.....	Lbs. Br. Stone	at	\$
.....	Lbs. Sand	at	\$
.....	Bags Cement	at	\$
.....	Paving Brick	Mack Red Asphalt } at	\$
.....	Lead Joints	at	\$
.....	Leadite Joints	at	\$
.....	2 Hrs. Foreman	at	\$ 1.25
.....	7 Hrs. Common Labor	at	\$ 3.25
.....	Hrs. Common Labor	at	\$
.....	Hrs. Mason	at	\$
.....	Hrs. Mason's Helper	at	\$
.....	Hrs. Compressor	at	\$
.....	Compensation Ins		\$ 12
.....	Trucking		\$ 1.00
.....	Builders' Use of Water	Partake	\$ 5.00
Total \$				19.84

79-175 17 Sept. 23 19

Labor and Material Report

13 Rem. at the tap



Main Elev of Main at tap

Gate at ● ● Gate at

● Curb Box

Old tap dis - connected