

**Labor and Materials**

1	Copper } Connection.....	3		\$ 3.20
	Lead } .....	1		
1	Curb } Cock	2		\$ 1.00
	Valve			
	T. S. & V. } .....	2		
1	Service Box } Short 3 1/2 x 4 1/2			\$ 1.00
	Old returned } Long 4 1/2 x 5 1/2			
	Butt-on Adway } .....			
27	Ft. .... in. } Copper	2		\$ 1.94
	Galv. Iron			
	Cast Iron } Pipe at.....	6		
	Nipples..... in. at.....			\$ .....
	Bushings..... to..... in. at.....			\$ .....
	Red'g } Couplings..... to..... in. at.....			\$ .....
	Inc'g } .....			
	Union..... in. at.....			\$ .....
	Meter..... in. at.....			\$ .....
	Lbs. Br. Stone at.....			\$ .....
	Lbs. Sand at.....			\$ .....
	Bags Cement at.....			\$ .....
	Paving Brick } Mack			\$ .....
	Red			
	Asphalt } at.....			
	Lead Joints at.....			\$ .....
	Leadite Joints at.....			\$ .....
2	Hrs. Foreman at.....	6 2/2		\$ 1.25
2	Hrs. Common Labor at.....	4 0		\$ 1.00
16	Hrs. Common Labor at.....	40 1/2		\$ 6.50
	Hrs. Mason at.....			\$ .....
	Hrs. Mason's Helper at.....			\$ .....
	Hrs. Compressor at.....			\$ .....
	Compensation Ins.....			\$ 2.3
	Trucking.....			\$ 1.00
	Builders' Use of Water.....			\$ .....
Total				\$ 21.52

28-79

18

Labor and Material Report July 13 1929

16 Kennedy Ave



4 Main

Elev. of Main at tap 5.3

Gate at ●

● Gate at

● Curb Box

Old Street Tap  
Shut off

23' 30' 3"