

Labor and Materials

1. Copper } Connection $\frac{3}{4}$ in	\$ 96
1. Lead } Connection $\frac{3}{4}$ in	\$ 96
1. Curb { Cock Valve } $\frac{3}{4}$ in	\$ 133
	{ F.S.&V. }
Service Box { Short $3\frac{1}{2} \times 4\frac{1}{2}$ }	\$ 135
Old returned { Long $4\frac{1}{2} \times 5\frac{1}{2}$ }	
	{ Buff. or Edwa. }
27 Ft. $\frac{3}{4}$ in. { Copper Galv. Iron } Pipe at 15	\$ 405
	{ Cast Iron }
Nipples in. at	\$
Bushings to in. at	\$
Red'g Inc'g } Couplings to in. at	\$
Union in. at	\$
Meter in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack Red Asphalt } at	\$
Lead Joints at	\$
Leadite Joints at	\$
3 Hrs. Foreman at 62	\$ 186
16 Hrs. Common Labor at 45	\$ 720
Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. Masons Helper at	\$
Hrs. Compressor at	\$
Compensation Ins	\$ 28
Trucking	\$
Builders Use of Water Patch	\$ 5
Total	\$ 2305

99-36 22

Labor and Material Report *Cost 30* 1936

20 Hammett Ave 2nd Fl

22



6" Main

Elev. of Main at tap 6'

Gate at • Gate at •

TAX ID # 302.12-20-8

• Curb Box.

old shut off

*OUTSIDE CLEANOUT
NEXT TO CURB BOX*

1-20-2016