

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
	Lead				
1	Curb	} Valve	3/4 in.	\$	
		T. S. & V.			
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				
		Long 4 1/2 x 5 1/2			
		Buff or Rdway			
27	3/4 in.	} Pipe at		\$	
	Nipples	in. at		\$	
	Bushings	to	in. at	\$	
	Red'g	} Coupl'gs	to	in. at	\$
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap by Gissard & Co.			\$	
	11-28-60			\$	
	O'head			\$	
				\$	

St. Kenworthy  
 Ave. No. 8

Name of Owner Gordon C. Kiltz.

Labor and Mat'l. Report Nov. 28 1960.

4" C.I. Main

Elev. of Main at tap 5'

Gate at • • Gate at

• Curb Box

LSM-5C-2-5-56