

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$
1	Lead			
1	Curb	} Cock	3/4 in.	\$
		T.S. & V.		
Some	Service box	} Short 3 1/2 x 4 1/2	}	\$
Old returned				
28	Ft. 3/4 in.	} Copper	} Pipe at	\$
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g	} Coupl'gs	to in. at	\$
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
	Lead Joints at		\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1 at		\$	
	Hrs. Water Maint. Man-2 at		\$	
	Hrs. Garage Foreman at		\$	
	Hrs. Labor— at		\$	
	Hrs. Compressor at		\$	
	Compensation Ins. at \$	per C	\$	
	Trucking		\$	
	Pav't Patch		\$	
	Top made Aug 11 1958		\$	
	By Gifford & Co		\$	
	O'head		\$	

St.
Pl.
Ave. No. 15

Name of Owner Knight
Mrs William Roach.

Labor and Mat'l. Report Aug 11 1958

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-5C-2-5 56