

LABOR AND MATERIALS

1 Copper	{ Connection	$\frac{3}{4}$	\$ 2.29
1 Lead	{		
1 Curb	{ Cock Valve	$\frac{3}{4}$ in.	\$ 2.70
	{ F.S. & V.		
1 Service box	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$ 4.25
Old returned	{ Long $4\frac{1}{2} \times 5\frac{1}{2}$		
	{ Buff or Rdway		
24 Ft. $\frac{3}{4}$ in.	{ Copper	Pipe at 35	\$ 8.40
	{ C.I.		
	{ C.I.		
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g	{ Coupl'gs to in. at		\$
Inc'g	{		
Union	in. at		\$
Meter	in. at		\$
Lead Joints at			\$
Compound Joints at			\$
4 Hrs. Water Maint. Man—1 at			\$
1.62 Hrs. Water Maint. Man—2 at			\$ 4.08
1.91 Hrs. Labor at			\$ 10.92
Hrs. Labor at			\$
Hrs. Compressor at			\$
Compensation Ins. at \$	per C.		\$ 1.33
Trucking			\$ 8.40
Pav't Patch			\$
Tap by <i>Morgan</i>			\$
O'head			\$
			\$ 42.37

St. 14
 Ave. No. 48

Name of Owner Edwards.

Labor and Mat'l. Report June 13 1950

6 Main Elev. of Main at tap 5

Gate at ● Gate at ●

TAX ID # 309.7-10-10

● Curb Box

LSM-6C 10-21-49