LABOR AND MATERIALS

1 Copper ~~Lead~~	Connection 3/4	$ 1.31
1 Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ }	3/4 in.	$ 1.75
1 Service Box Old returned { Short 3½x4½ / Long 4½x5½ / Buff. or Rdway }		$ 1.60
10 Ft. 3/4 in. { Copper / Galv Iron / ~~Cast Iron~~ }	Pipe at 18	$ 1.80
____ Nipples ____ in. at		$
____ Bushings ____ to ____ in. at		$
____ Red'g / Inc'g } Couplings ____ to ____ in. at		$
____ Union ____ in. at		$
____ Meter ____ in. at		$
____ Lead Joints at		$
____ Leadite Joints at		$
____ Hrs. Foreman at		$
3 Hrs. Chauffeur at	62½	$ 1.87
____ Hrs. Tapper at		$
6 Hrs. Labor at	45	$ 2.70
____ Hrs. Labor at		$
____ Hrs. Compressor at		$
____ Compensation Ins.		$ .14
____ Trucking		$ 1 —
____ Builders Use of Water	½ Patch (Sewer)	$ 2 50
Tap by Penna		$
		$
		$
		$ 14.67

B.4 - 1940

St. 51
Pl.
LaRose Ave. No. 28

Name of Owner

H Hart

Labor and Mat'l. Report Oct 16 1940

6 Main Elev. of Main at tap 4

Gate at ● ● Gate at

● Curb Box