

Labor and Materials

1	Lead Connection		\$
1	Curb Cock		\$
1	Service Box	Long 4 1/2 x 5 1/2	\$
32	3/4 in. G. I. Pipe at		\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Rcd'g Coup	to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone at		\$
	Cu. Yds. Sand at		\$
	Bags Cement at		\$
	Paving Brick	{ Mack Red Asphalt } at	\$
	Hrs. Foreman at		\$
2 1/2	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
3	Hrs. Penar	at	\$
	Hrs.	at	\$
	Builders' Use of Water		\$ 1.50
	Truck	at	\$ 1.00
		at	\$
		at	\$
		at	\$
	Total		\$

Labor and Material Report

1923

July 7
11 Lake Ave.



6 Main Elev. of Main at tap 4
Gate at ● Gate at ●

● Curb Box

New house.