

Labor and Materials

1	Copper Lead	Connection	2	\$	2.60
1	Curb Valve	4 in.	4	\$	2.27
1	Service Box	Short 3/4x4 1/2		\$	1.38
	Old returned	Long 1 1/2x3 1/2			
		Build. or Rdway			
7	Ft. in.	Copper Galv. Iron Pipe at	3	\$	1.26
		Cast Iron	4		
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
3	Hrs. Foreman	at		\$	1.88
7	Hrs. Common Labor	at Tapper		\$	3.50
6	Hrs. Common Labor	at		\$	2.70
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
3	Hrs. Compressor	at		\$	4.50
	Compensation Ins.			\$	25
	Trucking			\$	1
	Builders' Use of Water	Pitch		\$	73
				\$	—
	Total			\$	44.34

31-214 2478' *October 13 1931*

Labor and Material Report

18 *Lawrence St.*

12 Main

Elev of Main at tap

Gate at ● Gate at ●

● Curb Box

Old tap dis-connected.