

Labor and Materials

Copper } Connection.....	?	\$ 96
Lead }		
Curb { Cock }		\$ 1.33
{ Valve }		
{ T.S.&V. }		
Service Box { Short 2 1/2 x 4 1/2 }		\$ 1.35
Old returned { Long 4 1/2 x 5 1/2 }		
{ Built on Sidway }		
7 Ft. in. { Copper } Pipe at 15		\$ 2.55
{ Galv. Iron }		
{ Cast Iron }		
Nipples in. at		\$
Bushings to in. at		\$
Red'g } Couplings..... to in. at		\$
Inc'g }		
Union..... in. at		\$
Meter..... in. at		\$
Lbs. Br. Stone at		\$
Lbs. Sand at		\$
Bags Cement at		\$
Paving Brick { Mack } at		\$
{ Red }		
{ Asphalt }		
Lead Joints at		\$
Leadite Joints at		\$
8 Hrs. Foreman (at 6 1/2 hr)		\$ 5.00
2 Hrs. Common Labor at 50		\$ 1.00
17 Hrs. Common Labor at 45		\$ 7.65
Hrs. Mason at		\$
Hrs. Masons Helper at		\$
7 Hrs. Compressor at 2 1/2 hr		\$ 1.75
Compensation Ins		\$.42
Trucking		\$ 4.00
Builders Use of Water Patch		\$ 4.00
Total \$		32.01

Labor and Material Report

29/86 32
May 19 1926

24 Trammance St



12 Main

Elev. of Main at tap 4 1/2

Gate at ●

● Gate at

● Curb Box

old shut off at main

TAX ID # 303.17-1-46