

LABOR AND MATERIALS

| | | | | | |
|----|------------------------------|--------------|--|--------------|----------|
| 1 | Copper Lead | } Connection | $\frac{3}{4}$ | | \$ 1.80 |
| 1 | Curb | { Cock Valve | $\frac{3}{4}$ in. | | \$ 1.96 |
| | | { T. S. & V. | | | |
| 1 | Service Box | } | Short $3\frac{1}{2} \times 4\frac{1}{2}$ | } Pipe at 19 | \$ 1.82 |
| | Old returned | | Long $4\frac{1}{2} \times 5\frac{1}{2}$ | | |
| | | | Buffer Rdway | | |
| 25 | Ft. | | $\frac{3}{4}$ in. | | \$ 4.75 |
| | | | | | |
| | Nipples | | | | |
| | Bushings | | | | |
| | Red'g Inc'g | } | Couplings | | |
| | | | to | | |
| | Union | | | | |
| | Meter | | | | |
| | Lead Joints | | | | |
| | Leadite Joints | | | | |
| | Hrs. Foreman | | | | |
| 18 | Hrs. Chauffeur | | 68.34 | | \$ 12.38 |
| | Hrs. Tapper | | | | |
| 15 | Hrs. Labor | | 60 | | \$ 9.00 |
| | Hrs. Labor | | | | |
| | Hrs. Compressor | | | | |
| | Compensation Ins. | | 2.69 | | \$ 57 |
| | Trucking | | | | \$ 1.00 |
| | Builders Use of Water | | | | \$ 15.75 |
| | Tap 1/2" Brass | | | | |
| | Used on Curb to Connect | | | | |
| | 4 ft 3/4" Gal. Pipe + 3" Nip | | | | |
| | 3" Flange + 1-3/4" Flange | | | | |
| | | | | | \$ 49.03 |

11-144

St. 33
 Pl.
 Ave. No.

Lawrence

Name of Owner

O. Malley

Labor and Mat'l. Report June 24 1944

12
Main
Elev. of Main at tap 6

Gate at ●
● Gate at

● Curb Box