

Labor and Materials

Copper	Connection	3	\$ 1.33
Lead		4	
Curb	Cock Valve	8	\$ 1.58
		4	
Service Box	Short 3 1/2 x 4 1/2		\$ 1.36
Old returned	Long 4 1/2 x 5 1/2		
	Bull. or Rdway		
25 Ft. 3/4 in.	Copper Galv. Iron Cast Iron		\$ 2.38
	Pipe at		
	Nipples		\$
	Bushings		\$
	Red'g Inc'g		\$
	Couplings		\$
	Union		\$
	Meter		\$
	Lbs. Br. Stone		\$
	Lbs. Sand		\$
	Bags Cement		\$
	Paving Brick		\$
	Lead Joints		\$
	Leadite Joints		\$
4	Hrs. Foreman		\$ 2.50
9	Hrs. Common Labor		\$ 4.50
8	Hrs. Common Labor		\$ 3.60
	Hrs. Mason		\$
	Hrs. Masons Helper		\$
	Hrs. Compressor		\$
	Compensation Ins		\$ .33
	Trucking		\$ 1.-
	Builders Use of Water	Patch	\$ 5.-
Total			\$ 23.58

33-68

38

25 19 33

Labor and Material Report Aug 19

30 Lawrence St



Lawrence St

Cherry St.

12 Main

Elev. of Main at tap 4

Gate at ●

● Gate at

● Curb Box

old Tap shut off at Main

TAX ID # 303.17-2-22

*[Signature]*