

Labor and Materials

Copper } Connection. 3	\$ 3.20
Curb } Cock } 1/4 in. 2	\$ 1.00
} Valve } T. S. & V. }	
Service Box } Short 3 1/2 x 4 1/2	\$ 1.30
Old returned } Long 4 1/2 x 5 1/2	
} Buff or Rdway }	
2 } Ft. in. } Copper } Pipe at 3/4	\$ 5.06
} Galv. Iron }	
} Cast Iron }	
Nipples..... in. at.....	\$ .
Bushings..... to 1/4 in. at 1/2	\$ .08
Red'g } Couplings..... to..... in. at.....	\$ .
Inc'g }	
Union..... in. at.....	\$ .
Meter..... in. at.....	\$ .
Lbs. Br. Stone at.....	\$ .
Lbs. Sand at.....	\$ .
Bags Cement at.....	\$ .
Paving Brick } Mack } at.....	\$ .
} Red }	
} Asphalt }	
Lead Joints at.....	\$ .
Leadite Joints at.....	\$ .
1 Hrs. Foreman at..... 62.5-	\$ .62
16 Hrs. Common Labor at..... 5.0	\$ 8.00
Hrs. Common Labor at.....	\$ .
Hrs. Mason at.....	\$ .
Hrs. Mason's Helper at.....	\$ .
Hrs. Compressor at.....	\$ .
Compensation Ins..... 24	\$ 24
Trucking..... 1.00	\$ 1.00
Builders' Use of Water.....	\$ .
Total \$ 20.50	

26-62 48 June 2 19

Labor and Material Report

42 Lawrence St

Lawrence St

28' 5" 20'-7"

Curb Box

Walnut St

4 Main Elev. of Main at tap 11.5

Gate at ● Gate at ●

● Curb Box

Fluke Bros