

LABOR AND MATERIALS

1 Copper } Connection 2" \$  
 Lead }  
 1 Curb } Cook } 2 Wheel \$  
 Valve }  
 T.S. & V. }  
 2 Service box } Short 3 1/2 x 4 1/2 }  
 Old returned } Long 4 1/2 x 5 1/2 }  
 Buff or Rdway } \$  
 5 Ft. 2" in. } Copper } Pipe at \$  
 G.I. }  
 G.I. }  
 2 Nipples 2 in. at 1-6" - 1-4" \$  
 3 Bushings 1-2" to 1" in. at \$  
 Red'g } 1 - 1" x 3/4" }  
 Inc'g } Coupl'gs } to in. at \$  
 Union } 1 - 1" x 3/4" }  
 in. at \$  
 1 Meter 3" in. at Brass Elbow \$  
 1 Lead Joints at Tee \$  
 1 Compound Joints at 2" Male \$  
 Adapter \$  
 Maintenance Foreman \$  
 Hrs. Water Maint. Man-1 at \$  
 Hrs. Water Maint. Man-2 at \$  
 Hrs. Garage Foreman at \$  
 Hrs. Labor at \$  
 Hrs. Compressor at \$  
 Compensation Ins. at \$ per C \$  
 Trucking \$  
 Pav't Patch \$  
 1-2" - 1/2" Dresser \$  
 Couplings \$  
 O'head \$  
 1-3/4" Curb Stop \$  
 1-3/4" Male Adapter \$  
 1-1/2" x 3" galv. Nipple \$  
 3'-3/4" K. Copper \$

St. Lawrence Ave. No. 76  
 Name of Owner  
 Labor and Mat'l. Report July 3 1958  
  
 12" Main  
 Elev. of Main at tap 4'  
 Gate at • Gate at  
 Tap on Lawrence St.  
 • Curb Box  
 3/4" Line off 2" line on street side of 2" Wheel Valve  
 LSM-5C-2-5-56