

Labor and Materials

Copper } Connection	3	\$ 2.60
Lead } Connection	3	\$ 2.60
Curb } Cock	1	\$ 2.30
Valve } P. S. & V.	1	\$ 2.30
Service Box } Short 3/4x1 1/2	1	\$ 1.40
Old returned } Long 1 1/2x5 1/2	1	\$ 1.40
Buff. or Rdway		
30 Ft. 3/4 in. Copper	3	\$ 4.77
Galv. Iron Pipe at	4	\$ 4.77
Cast Iron		
Nipples in. at		\$
Bushings to in. at		\$
Red'g } Couplings to in. at		\$
Inc'g }		\$
Union in. at		\$
Meter in. at		\$
Lbs. Br. Stone at		\$
Lbs. Sand at		\$
Bags Cement at		\$
Paving Brick } Mack		\$
Red		\$
Asphalt } at		\$
Lead Joints at		\$
Leadite Joints at		\$
4 Hrs. Foreman at		\$ 2.50
34 Hrs. Common Labor at		\$ 13.81
Hrs. Common Labor at		\$
Hrs. Mason at		\$
Hrs. Mason's Helper at		\$
Hrs. Compressor at		\$
Compensation Ins		\$.43
Trucking		\$ 1.00
Builders' Use of Water Patch		\$ 5.00
Total \$		33.81

79-179 105-107 Oct 5 19

Labor and Material Report

H-73 Lawrence

73-75 105-107

12" Main

Elev of Main at tap 4 1/2'

Gate at ● Gate at ●

● Curb Box

Old tap disconect