

LABOR AND MATERIALS

Copper } Connection	_____	\$	_____
Lead } _____			
Curb } Cock	} in.	\$	_____
} Valve			
} T. S. & V.			
Service box } Short 3½ x 4½	} _____	\$	_____
Old returned } Long 4½ x 5½			
10'6" Ft. 3/4 in. } Copper	} Pipe at	\$	_____
} G.I.			
} G.I.			
Nipples	in. at _____	\$	_____
Bushings	to _____ in. at _____	\$	_____
Red'g } Coupl'gs	} to _____ in. at _____	\$	_____
Inc'g }			
Union	in. at _____	\$	_____
Meter	in. at _____	\$	_____
_____		\$	_____
Compound Joints	at _____	\$	_____
Maintenance Foreman	_____	\$	_____
Hrs. Water Maint. Man—1	at _____	\$	_____
Hrs. Water Maint. Man—2	at _____	\$	_____
Hrs. Garage Foreman	at _____	\$	_____
Hrs. Labor—	at _____	\$	_____
Hrs. Compressor	at _____	\$	_____
_____		\$	_____
Trucking	_____	\$	_____
Pav't Patch	_____	\$	_____
_____		\$	_____
_____		\$	_____
_____		\$	_____
_____		\$	_____
_____		\$	_____

LAWRENCE

St. PL. Ave. No. 120

Name of Owner

G.F. SCHOOL

Labor and Mat'l. Report

1991

● Curb Box

Main Elev. of Main at tap _____
 Gate at ● Gate at

TAX ID # 303.17-7-4

● Curb Box